

仁淀川の水質調査の結果(R5年9月調査)

仁淀川町

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5
1	長者川	五味谷	● 0	● 2	● 0	● 1	● 1	● 0	● 0	● 0
2		森集落排水下	● 0	● 1	● 0	● 1	● 2	● 1	● 1	● 0
3	仁淀川本川	大渡ダム直下	● 2	● 1	● 1	● 0	● 3	● 3	● 3	● 2
4		寺村	● 0	● 1	● 1	● 0	● 2	—	—	—
5		旧吾川中学校下	—	—	—	—	—	● 2	● 2	● 0
6	土居川	田村集落排水下	● 0	● 0	● 1	● 2	● 0	● 2	● 2	● 2
7		安の川原	● 0	● 0	● 0	● 1	● 0	● 0	● 3	● 1
8	小郷川	本流合流地点の200m上流	—	—	—	—	—	● 4	● 1	● 1

越知町・佐川町

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5	
9	春日川	かわせみ前	● 2	● 2	● 2	● 2	● 1	● 3	● 4	● 2	
10		伏尾川	二ノ部	● 1	● 1	● 1	● 1	● 1	● 3	● 3	
11	佐川町	力岩	● 1	● 1	● 1	—	● 1	—	—	—	
12		柳瀬川	黒岩	—	—	—	—	—	● 3	● 3	● 3
13			西山耕	—	—	—	—	—	● 1	● 2	● 1
14	尾川川	小奥	● 1	● 0	● 2	● 1	● 1	—	—	—	
15		松ノ木	—	—	—	—	—	● 2	● 2	● 2	
16	仁淀川	宮ノ前公園上流	● 2	● 2	● 1	● 1	● 1	● 1	● 1	● 1	
17	越知町	梅ノ木谷川	上流	● 6	● 8	—	—	—	—	—	
		中流	● 6	● 8	● 4	● 4	● 4	● 2	● 4	● 2	
		下流	—	● 6	—	—	—	—	—	—	
18	坂折川	坂折川橋下	● 2	● 1	● 0	● 0	● 1	● 0	● 0	● 1	
19	柳瀬川	本流合流地点の200m上流	—	—	—	—	—	● 2	● 2	● 1	
20	黒瀬		—	—	● 0	—	—	—	—	—	

日高村

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5
21	日下川	役場付近	● 1	● 3	● 2	● 3	● 1	● 3	● 3	● 3
22		加茂小学校近辺	● 1	● 1	● 1	● 2	● 1	● 1	● 1	● 2
23	仁淀川	屋形船発着場	● 1	● 0	● 1	● 0	● 1	● 2	● 1	● 1

いの町吾北

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5
24	上八川川	大久保	● 1	● 1	● 2	● 2	● 1	● 1	● 1	● 2
25		広瀬	—	—	● 2	● 1	● 2	● 2	● 1	● 2
26	枝川川		● 1	● 2	● 1	● 2	● 2	● 1	● 0	● 0
27	高椽川		● 2	● 1	● 1	● 3	● 2	● 1	● 1	● 2
28	小川川		● 0	● 1	● 0	● 2	● 1	● 1	● 0	● 1

いの町伊野

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5
29	波川親水公園	清掃会場	● 1	● 1	● 0	● 3	● 4	● 0	● 1	● 1
30	奥田川	大坪橋	● 3	● 3	● 2	● 1	● 3	● 3	● 4	● 5
31	仁淀川	名越屋沈下橋	● 2	● 0	● 0	● 1	● 1	● 0	● 2	● 1
32	宇治川	伊野商業前	—	—	—	—	—	● 3	● 3	● 5
33		天神橋	—	—	—	—	—	● 2	● 3	● 3

高知市・土佐市

No.	採取地		H28	H29	H30	R1	R2	R3	R4	R5
34	永野川・積善寺川合流点		● 2	● 2	● 1	● 3	● 1	● 1	● 3	● 2
35	土佐市	波介川 水門	● 2	● 2	● 1	● 2	● 1	● 1	● 2	● 1
36		波介川 潮止堰	● 3	● 6	● 3	● 3	● 2	● 1	● 3	● 3
37	高知市	仁淀川 河口	● 3	● 2	● 0	● 2	● 3	● 1	● 4	● 3
38		新川川 行当水路	● 2	● 3	● 1	● 2	● 3	● 2	● 1	● 2
39		新川川 春野庁舎前	● 3	● 3	● 1	● 2	● 2	● 3	● 3	● 4

COD(化学的酸素要求量)による評価

- 0～2 : きれい
- 3～4 : 少し汚れている
- 5～6 : 汚れている
- 7～ : かなり汚れている